

US 542 U.S. PTO  
09/133615

08/13/98

Fig. 1




Fig. 2




Fig. 3





FIG. 4

190






Fig. 8




Fig 5




Fig. 6




Fig 7






FIG. 12






FIG. 13










FIG. 18





FIG. 19



SEALING SECTION



CUT-EN

1 To  
Drills  
motor




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25






FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30



FIG. 31




FIG. 32






FIG. 33






FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40





FIG 39a








FIG. 42







FIG. 43




**FIG. 44**







**FIG. 45**




**FIG. 46**




**FIG. 47**









**FIG. 51**




**FIG. 52**




**FIG. 50**



**FIG. 53**



**FIG. 57**



**FIG. 56**

Je542 U.S. PRO

09/133615



08/137/98

**ATTACHMENT C**